



Creating healthy spaces

NV RENSON® Sunprotection-Screens SA

Order confirmation

Confirmation date	14.11.2023	CP Interiors
Order number	29035	St. Saviour
Customer number	1001334	28 Rue des Pres. Tr. Est.
Your VAT number		JE2 7QN JERSEY
Currency	GBP	JERSEY
Project reference	SO15168 Whitney	
Order reference	Whitney	
Latest delivery date	27.11.2023	

coterms	DAP Jersey
Total net weight	1,336 KG
Total gross weight	1,380 KG

Delivery address

CP Interiors
St. Saviour
28 Rue des Pres. Tr. Est.
JE2 7QN JERSEY
JERSEY

RECEIVED
22 NOV 2023
SCANNED ☐

Overview

Material	Quantity	Net amount	VAT %
001000 6165 SEAL BRUSH + CLAMP PROFILE 3M	6,00 PC	136,80	
000 1674 END CAP GUTTER PIVOT SIDE L	4,00 PC	4,42	
003000 1675 END CAP GUTTER PIVOT SIDE R	4,00 PC	4,42	
Total before VAT		145,64	
VAT		0,00	
Total incl. VAT		145,64	

Free of VAT, export

The General Terms and Conditions of Sale are integral part of our agreement. See Professional Portal at <http://www.renson.eu/>



Creating healthy spaces
NV Renson® Sunprotection-Screens SA

Order confirmation

29035

14.11.2023

PAYMENT INFORMATION

Payment term

30 days end of month

For questions or remarks regarding this document, please send an email to outdoor-uk@renson.be

The General Terms and Conditions of Sale are integral part of our agreement. See Professional Portal at <http://www.renson.eu/>

NV Renson® Sunprotection-Screens SA • IZ 1 Flanders Fields • Kalkhoevestraat 45 • B-8790 Waregem
+3256627111 • info@renson.eu • www.renson.eu

VAT BE 0432.549.526 • RPR Gent, afdeling Kortrijk • ING BELGIË IBAN BE08 3850 3006 5013 - BIC BBRUBEBB



Creating healthy spaces
NV RENSON® Sunprotection-Screens SA

Order confirmation

29035

14.11.2023

Detail

Item	Material	Unit price	Quantity	Gross amount	Discount %	Net amount
001000	6165 SEAL BRUSH + CLAMP PROFILE 3M Commodity code 39259010	38,00 GBP / 1 PC	6,00 PC	228,00	40	136,80
002000	1674 END CAP GUTTER PIVOT SIDE L Old material nr G6021241 Commodity code 39269097	Ohter plastic articles	4,00 PC	7,36	40	4,42
003000	1675 END CAP GUTTER PIVOT SIDE R Old material nr G6021242 Commodity code 39269097	Ohter plastic articles	4,00 PC	7,36	40	4,42

Scott Ruderham

X Parts ordered
14/11/23

From: Scott Ruderham
Sent: Monday, 13 November 2023 14:07
To: Lisa Whitney
Subject: RE: SO15168 Parts Require for Repair

Hi Tony & Lisa

I have been speaking to Renson who have advised on the parts required for repair from the storm damage.

I can confirm we will need to replace the gutter end caps and draught excluders. These parts are £291.28 + GST. As advised this will be done at an hourly rate to rectify of £69.00 per hour per fitter. Any time accrued for rectifying the previous leak will be not included and waived.

Please can you let me know at your earliest convenience if you wish to proceed. The order lead time is approx. 10-14 days.

Kind Regards
Scotty
CP Interiors

From: Lisa Whitney <whitney.jsy@gmail.com>
Sent: Wednesday, 8 November 2023 18:24
To: Scott Ruderham <scott@cpinteriors.je>
Subject: Re: SO15168 Parts Require for Repair

Yes that would be great thanks. Will wait to hear from you.

Thank you

Lisa

Sent from my iPhone

On 8 Nov 2023, at 09:31, Scott Ruderham <scott@cpinteriors.je> wrote:

Dear Tony & Lisa

Following on from my team's visit yesterday to look at the glass house,

Ben has identified what parts need replacing due to the storm damage and also the amount of time required on site.

He thinks a day for him and Andy once the parts are here is what is required.

Ben and I need to get together to go through the parts list and place an order.

I do have to inform that the parts affected by storm will need to be chargeable as not covered under warranty.

Any labour and or parts required for the leak that has been persistent will not be chargeable.