

# Fault Report

Customer Name: Crone	Date: 26.11.25
Customer Reference: 360792	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: RH Bed Bay and LH Bed Bay, Shutter Batterns	
Fault Description: Battens needed see below.	
Action to correct: Battens Needed: ✓80mm x1418mm, Rh Bed Bay 1 ✓20mm x 690mm, Rh Bed Bay 1 ✓10mm left to .30mm right x 660mm, Rh Bed Bay 3 ✓2nr 70mm bottom to 85mm top x 1454mm, Lh Bed Bay 1 Give at least 1hr to complete as there is caulking to do as well.	

- Slat need fixed.

living room RH side - .

# Baileys

34 HIGH STREET,  
SPENNYMOOR,  
DURHAM DL16 6DB  
TEL: 01388 813267 or 0191 258 5956  
enquiries@baileys-blinds.co.uk  
www.baileys-blinds.co.uk

DATE MEASURED/ORDERED  
**5/18/25**

Measured By:  
**DAVE**

360792

**SPECIAL INSTRUCTIONS**

fit 50mm from  
FRAME  
  
CUST WANT'S ALL  
FRAMES THE SAME  
  
WORKING AFTER  
FITTING EXPLAINED

FOUR	
NET	
PRESS	
RADIO	
MAG.	
VAN	
RECO.	
SHOP	
TV	
YELL P	
OTHER	

Customer's Name **CRONE**  
Address **7. CRANWELL DRIVE**  
**WIDEOPEN**  
Post Code **NE13 6AR**

CURTAINS	
PLEATED	
ROLLERS	
ROMANS	
SHUTTERS	X 10
VENETIAN	
VERTICALS	
VISION	
WOODEN	

Tel. home  
Tel. work  
mobile **07796 567806**  
email

Fitters Req.	Est. Time	Special RA (separate sheet)
--------------	-----------	-----------------------------

alum	anthracite	black	brown	champ-gold	chrome	silver	white	recess size	motorised	wood fix	stone fix	brackets top	brackets face
								<b>HL</b>					

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Price
LH FRONT BAY	1678	1165	89	NO BREAK	LRR	684.00	
LOUSE RM ①	580	1615	+	1225	L	327.00	
②	1568	1615	→	1225	LRR	806.00	
③	887	1615	→	1225	L	382.00	
LH BED RM	577	1454	+	1075	L	294.00	
②	1565	1454	→	1075	LRR	796.00	
③	582	1454	→	1075	L	296.00	
RHD BAY ①	617	1418	→	1045	L	307.00	
②	1449	1418	→	1045	LRR	720.00	
③	610	1418	→	1045	L	302.00	
				5x70x1615 SIDE LOUNGE BAY		60.00	
				5x70x1454 LH BED BAY SIDE		60.00	
				5x70x1418 RM		60.00	
				TOTAL		5124.00	
				26% DISC		1302.40	
				TOTAL		4100.00	
				+ 10'6 EASY FLT		494.00	

\* 01/11/25 - SJ.  
Fitted - see fault report.

SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. IF YOU REFUSE TO ALLOW A SAFETY DEVICE TO BE FITTED, THEN THE GOODS WILL NOT BE INSTALLED, AND UNDER THESE CIRCUMSTANCES YOU WILL STILL BE LIABLE TO PAY THE FULL PRICE UNDER YOUR CONTRACT. YOU ARE STILL BOUND TO ACCEPT DELIVERY OF THE GOODS AND TO PAY FOR BOTH THE FITTING AND INSTALLATION EVEN ALTHOUGH INSTALLATION HAS NOT BEEN CARRIED OUT.

It is our responsibility to supply you with goods that meet your consumer rights. If you have any concerns that we have not met our legal obligations please contact us. Unless stated, goods and installation service come with 12 month warranty. Full T's & C's on our website. I have ordered the above goods and agree to pay 80% deposit and the remaining balance when confirming fitting appointment. If payment is not made in full at that time Baileys Blinds has the right to remove the goods until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE **£4594.00** PRICE ACCEPTANCE Customer's Signature

DEPOSIT **£2297.00** R. Crone

BALANCE **£2297.00** CASH  CHEQUE  CARD

**ORDER BALANCE TO BE PAID FOR AT FITTING CONFIRMATION**

