

GC 6411

Fault Report

Customer Name: CAMPBELL	Date: 21-11-22
Customer Reference: 6411	Fitter: DAVID
Salesperson: MIKE	Salesperson called: Yes/No NO ANSWER
Inputting Error <input checked="" type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: KITCHEN SHUTTER	
Fault Description: LARGE KITCHEN SHUTTER IS WRONG CONFIG NEEDS TO BE LLLR TO GET PAST KITCHEN TAP	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: NEEDS NEW DOORS AT LLLR	