

GC 6411

CAMPBELL IR

Fault Report

Customer Name: CAMPBELL	Date: 28-8-23
Customer Reference: 6411 6411	Fitter: GRENNE
Salesperson: MIKE	Salesperson called: Yes/No
Blind Type and number: CONSERVATORY BLIND 1.	
Fault Description: BLIND FRAYING AT EDGES.	
Action to correct: REPAIR.	
Problem fixed on site: Yes/No	
Further action required:	