

Fault Report

Customer Name: Macdonald	Date: 25/1/24
Customer Reference: 7252	Fitter: David
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Vertical 2	
Fault Description: Slats on bedroom vertical have been made to long	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: Needs new slats made with correct size	