

CIC 7327

DOUGLAS/R

ON 027589R

Fault Report

FITTER NAME: David	FITTING DATE: 10/10/24
Customer Name: Douglas	
Customer Ref: 7327	
Salesperson: Ronnie	Salesperson called: Yes/No
Blind Type and number: Curtain livinroom right	
Problem fixed on site: Yes/No	
Fault Description Curtain has been measured to short	
Action to Correct:- New curtains needed 2120 x 1550	