

Fault Report

UC 7479
LARKIN/R
ON 8/02/24

FITTER NAME: David	FITTING DATE: 18/03/2025
Customer Name: Larkin	
Customer Ref: 7479	
Salesperson: Ronnie	Salesperson called: Yes/No
Blind Type and number: R bed R infusion wood	
Problem fixed on site: Yes/No	
Fault Description No pelmet clips to attach the pelmet in the box.	
Action to Correct:- Need 2 packs of pelmet clips	