

UL POST  
KNEX/R

# Fault Report

Amy

Customer Name: KNEX	Date: 19-6-25
Customer Reference: 7857	Fitter: DAVID
Salesperson: RONNIE	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: SOMFY MOTOR	
Fault Description: WRONG MOTOR ORDERED  CUSTOMER'S ORIGINAL CHARGE IS FAULTY	
Action to correct:  ROLL UP 28 RTS MOTOR NEEDED  NEW CHARGE MODEL NUMBER - CQ15-150048-AX NEEDS	

