

Fault Report

Customer Name: ATKIN	Date: 25-9-25
Customer Reference: 8016	Fitter: DAVID
Salesperson: office	Salesperson called: Yes/No <input checked="" type="checkbox"/>
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: GYM SHUTTER MIDDLE DOOR (DOOR 2)	
Fault Description: LOUVRES ARE WRONGS SIZE	
Action to correct: 2 NEW LOUVRES + FITTINGS FOR THE LOUVRES 491mm IS THE EXACT WIDTH OF THE LOUVRES ON THE DOOR	