

UC 8016

Atkin 12

# Fault Report

Customer Name: <u>ATKIN</u>	Date: <u>25-9-25</u>
Customer Reference: <u>8016</u>	Fitter: <u>DAVID</u>
Salesperson: <u>office</u>	Salesperson called: <u>Yes/No</u> <u>Yes</u>
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: <u>Yes/No</u>	
Blind Type and number: <u>GYM SHUTTER MIDDLE DOOR (DOOR 2)</u>	
Fault Description: <u>LOUVRES ARE WRONGS SIZE</u>	
Action to correct: <u>2 NEW LOUVRES + FITTINGS FOR THE LOUVRES</u> <u>491mm IS THE EXACT WIDTH OF THE LOUVRES ON THE DOOR</u>	