

# Fault Report

|   |  |
|---|--|
| Customer Name: MCKENZIE   | Date: 6-11-25                                      |
| Customer Reference: 8050  | Fitter: DAVID                                      |
| Salesperson: RONNIE   | Salesperson called: Yes/ <del>No</del>             |
| Order Inputting Error <input type="checkbox"/>  | Mismeasure <input type="checkbox"/>                |
| Production Error <input type="checkbox"/>   | Supplier Error <input checked="" type="checkbox"/> |
| Fitting Error <input type="checkbox"/>  |  |
| Problem fixed on site: Yes/No   |  |
| Blind Type and number:<br>CURTAIN   |  |
| Fault Description:<br><br>MADE 2970 INSTEAD OF 2870<br><br>UNABLE TO MOVE POLE UP BECAUSE OF WINDOW FRAME |  |
| Action to correct:<br><br>CURTAINS NEED ADJUSTED  |  |

