

~~16/1~~ 20/11.

Fault Report

Customer Name Gocksman	Date; 16/11/25
Customer Reference: 25135	Fitter Michael
Salesperson: Stuart	Salesperson called: Yes/No --
Fault Description: blinds on one of the windows are too close to the curtains. 2 of the hooks for holding the slats are twisted.	
Action to correct: Customer had adjustable curtain rail so moved it further out	
Problem fixed on site: <input checked="" type="radio"/> Yes/No	
Further action required: NO	