

# Fault Report

Customer Name LATTO	Date; 03/02/2025
Customer Reference: 25204	Fitter MICHAEL
Salesperson: MICHAEL	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: Both rails came as 1580mm instead of 1475mm???	
1 set of curtains came as 2520mm instead of 2570mm	
Action to correct: Remake curtains for living room (1) as 2570mm Rails were cut to correct size onsite	
Problem fixed on site: <input checked="" type="radio"/> Yes <input type="radio"/> No	
Further action required: Yes, Remake curtains at correct drop figure out why rails were made to a completely different size than what was ordered. Return to customers house and rehang correct length of curtains	



# GRAMPIAN BLINDS

DATE  
MEAS  
14

Unit 1 B, Mugiemoos Road, Al  
Tel: 01224 662884 - Fax: 012  
Email:enquiries@grampian-blin

Customer's Name Kirsteen

Address 10 Canton Terr  
Stonehaven

Post Code AB39 2HX

Tel. home	<u>01569 765976</u>
Tel. work	
mobile	
email	

ROM  
SHUTTE  
VENETI/  
VERTIC  
VISIO  
WOOD

alum	anthracite	black	brown	champ-gold	chrom

Room	Width	Drop	Slat Size	
Living	14'75	<del>25'70</del>	Curt	Pencil P
	14'75	25'70	Track	
Dining	14'75	<del>25'70</del>	Curt	' Lo
	14'75	25'70	Track	

BLAZE | 4501526749 | 10




\* 8509285 - A \*

W: 1475 D: 2520

977DPI-B/1

FBR-1



58

59



61

62

63

7 8 9

10 1

2 3 4

5 6 7

8 9

10

