

# Fault Report

Customer Name MASON	Date; 13/12/24
Customer Reference: 25213	Fitter MICHAEL
Salesperson: STUART	Salesperson called: Yes/No <input checked="" type="radio"/>
Fault Description: Roller too tight to clear upstand	
Action to correct: remake @ 1184 recess	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes	