

Fault Report

Customer Name DICKENS	Date; 07/02/25
Customer Reference: 25374	Fitter MICHAEL
Salesperson: STUART	Salesperson called: Yes/No <input checked="" type="radio"/>
Fault Description: Customer wanted into blinds 1&2 to be 2 way control	
Action to correct: Remake as 2-way control	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes, remake blinds as 2 way control return to customer and refit blinds.	