

# Fault Report

Customer Name CROOK	Date; 24/07/25
Customer Reference: 0541	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/No <input checked="" type="radio"/> No
Fault Description: VERTICALS NEED BROWN EXTENSION BRACKETS NOT STANDARD BRACKETS	
Action to correct: SEND UP BROWN EXTENSION BRACKETS	
Problem fixed on site: Yes/No <input checked="" type="radio"/> No	
Further action required: YES, SUPPLY NEW BRACKETS & RETURN TO FIT	