

Fault Report

Customer Name Mason	Date; 12/08/25
Customer Reference: 26005	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: Rail NOS for Big B/R 1 made at the wrong size. should be 1562 but is ~ 1585	
Action to correct: Cut down to 1562 Recess	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: cut down and return to fit.	