

Fault Report

Customer Name Robertson	Date; 01/10/25
Customer Reference: 26234	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes NO
Fault Description: Blind too big	
Action to correct: Cut down to 2370 recess	
Problem fixed on site: Yes <u>No</u>	
Further action required: Cut down & return to fit ASAP	