

Fault Report

FITTER NAME: MICHAEL	FIXING DATE: 9/10/25
Customer Name: MCNAULTY	
Customer Ref: 26256	
Salesperson: LEWIS	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Wooden blinds 1-3	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Fault Description MISMEASURE OF LOUNGE WOODS. CAUSING GAPS WHICH CUSTOMER HAS COMPLAINED ABOUT.	
Action to Correct:- REORDER BLINDS @ 680 x 1618 recess } everything else 1890 x 1618 exact } as previous. 675 x 1618 recess }	