

Order Confirmation

HunterDouglas

Order Number	R22-204961	Customer Number	36294000
Reference 1	7218/REPAIR	Name	London Shades LLP
Reference 2	C22-123742	Address	London Shades LLP 54 Larkshall Road Chinsford E4 6PD UNITED KINGDOM.
Order Date	13-10-2022		

Line	Sales Item	Description	Quantity	Unit Price	Discount	Nett Price
1	REP004	Duette Blind Repair Repair action 1: No further action required Override: Yes Width: 0 Height: 0 Colour: OperationType: OperationLengthFixed: 0 OperationLengthFree: 0 OperationLengthStandard: 0 OriginalOperationLength: 0 OperationLengthSpecificPB: 0 OperationLengthFinal: 0 New width: 0 New height: 0 New colour: Child save component: Tensioner	2.000	29.00	0.00	58.00
2	V90026	Repair Collection Charge	1.000	25.00	0.00	25.00

VAT will be added at the rate prevailing at the date of invoice

Order Total

83.00

IMPORTANT Child Safety Notice - Risk Of Serious Hazard And Cause Of Injury To Children

To ensure compliance with EC Directive 2001/95, EC Decision 2011/477 and EN 13120:2014, all child safety devices and components MUST be assembled and installed in accordance with our instructions. We do not accept any liability for damages or costs arising from wrongful assembly and/or installation not performed by us.

Products suffixed as FSC are supplied/sold under FSC Chain of Custody certificate code NC-COC-014368