

SB 6461

HARRISON / R

SB 701SR

# Fault Report

Customer Name: Harrison	Date: 8/5/24
Customer Reference: 6461	Fitter: Ross
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Kitchen Roller	
Fault Description: Both brackets snapped	
Action to correct: order 2x vision face fix brackets	
Problem fixed on site: Yes/No	
Further action required:	