

Fault Report

SB 6913

MCKENZIE / R

SB 7381R

FITTER NAME: David	FITTING DATE: 18/09/24
Customer Name: Mckenzie	
Customer Ref: 6913	
Salesperson: Ronnie	Salesperson called: Yes/No
Blind Type and number: Roller 2	
Problem fixed on site: Yes/No	
Fault Description The blind has been made the wrong size than that was asked for. Its been made 907x525 instead of 907x1525	
Action to Correct:- New blind at 907x1525	