

Fault Report

SB 7127
DEWAR/R

SB8134R1

Customer Name: DEWAR	Date: 25-6-25
Customer Reference: 7127	Fitter: DAVID
Salesperson: RONNIE	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: VERTICAL SLATS	
Fault Description: SLATS ARE TOO LONG	
Action to correct: New size for blind is 2720 X 1953 with drop Recess size	