

Fault Report

Customer Name: Bennie	Date:
Customer Reference: 4828	Fitter: Mike
Salesperson: Mark E	Salesperson called: Yes/No
Blind Type and number: Vertical - Bedroom	
Fault Description: Headrail too narrow. Customer also surprised no chains on blinds May need follow up.	
Action to correct: Need vertical headrail @ 1145 (Recess) for Bedroom	
Problem fixed on site: Yes/No	
Further action required:	