

Fault Report

Customer Name: KARRI	Date: 11/15/22
Customer Reference: 4172	Fitter: Cameron
Salesperson: Cameron	Salesperson called: Yes/No N/A
Blind Type and number: wood ven 50mm 1	
Fault Description: Blind not corded correctly	
Action to correct: factory going to Attempt Repair	
Problem fixed on site: Yes/No <input checked="" type="radio"/> No	
Further action required: New blind : f factory Cannot repair	