

Rain 6492
Fotheringham.R

Fault Report

Customer Name: Fotheringham	Date: 29/6/22
Customer Reference: 6492	Fitter: Cameron
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Vert 1	
Fault Description: Blind too large for window Motor fouling on PVC window frame.	
Action to correct: New size taken Can it be cut down?	
Problem fixed on site: Yes/No	
Further action required: *Asked Factory To Cut Down*	