

Fault Report

Customer Name: Smith	Date: 27-5-22
Customer Reference: 6637	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: 4 ROLLER	
Fault Description: WRONG MATERIAL SHOULD BE MADDOX ALUMINUM B/O	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:	