

4314

Fault Report

Customer Name: Bremner	Date: 14/8/22
Customer Reference:	Fitter: CAMERON
Salesperson: CAMERON	Salesperson called: Yes/No
Blind Type and number: 25 25 ver 2	
Fault Description: civ blind has twisted ladders + both blinds stuttering ALOT on way down Every 40 or so mm	
Action to correct: Couldnt on site	
Problem fixed on site: Yes/No	
Further action required: Blinds returned to find solution.	