

SB15043R

RAIN 7778  
MORRISON/R

# Fault Report

Customer Name: Morrison	Date: 16/NOV/23
Customer Reference: 7778	Fitter: Dylan
Salesperson: Gary	Salesperson called: Yes/No
Blind Type and number: Vertical 2110 by 1495	
Fault Description: Slats 12 mil too short Customer refused.	
Action to correct: New slats 12 mil longer	
Problem fixed on site: Yes/No	
Further action required:	