

ED 5294
Souter JR

| | |
|---|---------------------------|
| Customer Name: Souter | Date: 16/07/25 |
| Customer Reference: 5294 | Fitter: Gary |
| Salesperson: Gary | Salesperson called: No |
| Blind Type and number: 1 x vert | |
| Fault Description: Front Bed should be 1005mm | |
| Action to correct: Remake slats only at 1005mm for front bed | |
| Problem fixed on site: | |
| Further action required: | |

Fault Report