

Fault Report

Customer Name: HUNTINGTON	Date: 18/5/22
Customer Reference: 43619	Fitter: DAVID.
Salesperson: DAVID	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Blind Type and number: VENETIAN #3	
Fault Description: BLIND ORDERED WITH LH CONTROLS - NEED + REORDERED WITH RH CONTROLS	
Action to correct: REORDERED SINGLE ALIND RH CONTROL	
Problem fixed on site: Yes/No	
Further action required:	