

Fault Report

Customer Name: <u>Castillo</u>	Date: <u>11/7/23</u>
Customer Reference: <u>45960</u>	Fitter: <u>AMO</u>
Salesperson: <u>Marzena</u>	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number: <u>1. VERTICAL</u>	
Fault Description: <u>reversed figures, mis measure</u> <u>old: 1086x2060</u> <u>New: 1060x2060.</u>	
Action to correct: <u>re order</u>	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: <u>re order</u>	