

Fault Report

Customer Name: Robb	Date: 14/07/23
Customer Reference: 46047	Fitter: AMO
Salesperson: Marzenci	Salesperson called: Yes/No
Blind Type and number: 2, Roller	
Fault Description: MIS MEASURE - reversed figures old: 1105x1300 new: 1150x1200	
Action to correct: re-work - ordered	
Problem fixed on site: Yes/No	
Further action required: yes - re work	