

Fault Report

Customer Name: SCOTT	Date: 25/7/23
Customer Reference: 46064	Fitter: AMO
Salesperson: Steven	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: CURTAINS Roman	
Fault Description: ordered 2x wrong colour	
Action to correct: re order	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: yes.	