

Fault Report

Customer Name: Gibson	Date: 31/08/23
Customer Reference: U4955	Fitter: AMO
Salesperson: David	Salesperson called: <input checked="" type="radio"/> Yes/ <input type="radio"/> No
Blind Type and number: 1, vision	
Fault Description: Fabric has come away from cassette, resulted in damage to fabric on LHS.	
Action to correct: return to Rainbow.	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes.	