

Fault Report

Customer Name: Riddoch	Date: 25/9/23
Customer Reference: L16433	Fitter: AMO
Salesperson: Marzena	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Roller, A113	
Fault Description: All bunds mis measured Also bunds are to be reversed roll Old: 720x1760, 1470x1760, 720x1760 New: 650x1760, 1340x1760, 649x1760	
Action to correct: Re ordered new sizes & reversed roll	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: yes.	