

Fault Report

Customer Name:	Clark
Customer Reference: 46337	Fitter: Amo
Salesperson David	Salesperson called: /No
Blind Type and number: Roller – no 7	
Fault Description: Got 8 blinds fitted 7 are lovely but blind no 7 of 8 has flaw down middle fabric	
Action to correct: Remake required	
Problem fixed on site: /No	