

Fault Report

Customer Name: Taylor	Date: 11/19/23
Customer Reference: 46354	Fitter: AMO
Salesperson: David	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: L. vertical	
Fault Description: Slats should be B10 - ordered as non B10. Headrail ordered brown but came white.	
Action to correct: re order bund	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes.	