

# Fault Report

Customer Name: Carol	Date: 11-10-23
Customer Reference: 46436	Fitter: AMO
Salesperson: Steven	Salesperson called: Yes/No
Blind Type and number: 8. wooden	
Fault Description: ordered wrong size <del>in</del> reversed figures.	
Action to correct: Re order	
Problem fixed on site: Yes/No	
Further action required: yes .	