

Fault Report

Customer Name: Brady	Date: 25-10-23
Customer Reference: 46565	Fitter: AMO
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: 4. roller	
Fault Description: roller been made wrong colour pics sent to Jennifer + sales	
Action to correct: re order.	
Problem fixed on site: Yes/No	
Further action required: yes - re make	