

Fault Report

Customer Name: Bridge	Date: 28.11.23
Customer Reference: T9132	Fitter: -
Salesperson: -	Salesperson called: Yes/No
Blind Type and number: 3. Pfit roller	
Fault Description: 1x Pfit roller. Pin hole in fabric	
Action to correct: Re order	
Problem fixed on site: Yes/No (No)	
Further action required: yes.	