

Fault Report

Customer Name: SMITH	Date: 28-2-24
Customer Reference: 47104	Fitter: AMO
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: 1,2 roller	
Fault Description: MIS MEASURE OLD: 1120 x 1080 NEW: 1170 x 1080	
Action to correct: Re order	
Problem fixed on site: Yes/No	
Further action required: yes.	