

# Fault Report

Customer Name: Vetchi AI	Date: 30-5-24
Customer Reference: 4701612	Fitter: Stuart
Salesperson: Steven	Salesperson called: <input checked="" type="radio"/> Yes/ <input type="radio"/> No
Blind Type and number: 63, Venetian	
Fault Description: 1x slot too much. Re make.	
Action to correct: Re order 1x bund	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes.	