

Fault Report

Customer Name: Perkins	Date: 12/1/24
Customer Reference: 48597	Fitter: N/A
Salesperson: Customer	Salesperson called: N/A
Blind Type and number: 1, 2, 3 Roller	
Fault Description: Customer ordered blinds as exact size, should be recess-asked if we can cut down	
Action to correct: AMO to cut - bit @ Grampian broken. Steven said put to Rainbow for more professional finish	
Problem fixed on site: NO	
Further action required: Yes. Needs cut down.	