

Fault Report

Customer Name: North Contracts	Date: 19-7-24
Customer Reference: 48607	Fitter: AMO
Salesperson: STUART	Salesperson called: NO
Blind Type and number: 2, roller.	
Fault Description: reversed Figures - ordered wrong OLD: 894x 1180 NEW: 984x 1180.	
Action to correct: re order	
Problem fixed on site: NO	
Further action required: NO.	

