

Fault Report

Customer Name: <i>WOODS</i>	Date: <i>22-7-24</i>
Customer Reference: <i>8 48533</i>	Fitter: <i>AMO</i>
Salesperson: <i>Steven</i>	Salesperson called: <i>NO</i>
Blind Type and number: <i>4. roller</i>	
Fault Description: <i>Hole in fabric @ blbar</i>	
Action to correct: <i>Re order new one</i>	
Problem fixed on site: <i>NO</i>	
Further action required: <i>yes.</i>	

