

# Fault Report

Customer Name SHARP	Date: 06/03/26
Customer Reference: SIS48	Filter MICHAEL
Salesperson: BILL	Salesperson called: Yes/No

Fault Description:

Scratch on bottom bar

Action to correct:

Replace bottom bar

Problem fixed on site: Yes/ No

Further action required:

Yes, replace bottom bar



# Fault Report

Customer Name: <i>SHARPA</i>	Date: <i>23/03/26</i>
Customer Reference: <i>51548</i>	Fitter: <i>MICHAEL</i>
Salesperson: <i>BILL</i>	Salesperson called: Yes/No <input checked="" type="radio"/>
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: <i>VISION</i>	
Fault Description: <i>BOTTOM BAR DAMAGED FABRIC</i>	
Action to correct: <i>NEW BLIND</i>	