

Fault Report

Customer Name Emmerton	Date; 09/04/26
Customer Reference: 51721	Fitter MICHAEL
Salesperson: BILL	Salesperson called: Yes/No
Fault Description: OFFICE LEFT & RIGHT SHOULD BE P/FIT	
Action to correct: Remake as P/FIT	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: Remake & return to fit.	

