

Fault Report

Customer Name: <i>MCLEAN</i>	Date: <i>14/04/26</i>
Customer Reference: <i>51399</i>	Fitter: <i>AMO</i>
Salesperson: <i>BILL</i>	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/ No	
Blind Type and number: <i>#6 STAIR LANDING ROLLER</i>	
Fault Description: <i>CORRECT SIZE ON ORDER AND LABEL ARRIVED TO SHORT IN DROP TUBE VISIBLE</i>	
Action to correct: <i>REORDER</i>	