

# Fault Report

Customer Name: <i>MCLEAN</i>	Date: <i>14/04/26</i>
Customer Reference: <i>51399</i>	Fitter: <i>AMO</i>
Salesperson: <i>BLL</i>	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No <input checked="" type="checkbox"/>	
Blind Type and number: <i>#7 BATHROOM ROLLER</i>	
Fault Description: <i>WRONG SIZE</i> <i>CORRECT SIZE <u>1771</u> DROP</i>	
Action to correct: <i>REORDER</i>	